

**DEPARTMENT OF THE TREASURY****Office of the Comptroller of the Currency****12 CFR Part 22**

[Docket IDs OCC–2020–0033, OCC–2020–0008]

**FEDERAL RESERVE SYSTEM****12 CFR Part 208**

[Docket No. R–1742, OP–1720]

**FEDERAL DEPOSIT INSURANCE CORPORATION****12 CFR Part 339**

RIN 3064–ZA16

**FARM CREDIT ADMINISTRATION****12 CFR Part 614****NATIONAL CREDIT UNION ADMINISTRATION****12 CFR Part 760**

RIN 3133–AF31, 3133–AF14

**Loans in Areas Having Special Flood Hazards; Interagency Questions and Answers Regarding Flood Insurance***Correction*

In Rule document 2022–10414, appearing on pages 32826–32895, in the issue of Tuesday, May 31, 2022, make the following correction:

On page 32895, in the third column, the signature block is corrected to read as set forth below:

**Michael J. Hsu,**

*Acting Comptroller of the Currency.*

By order of the Board of Governors of the Federal Reserve System.

**Ann E. Misback,**

*Secretary of the Board.*

Federal Deposit Insurance Corporation.

Dated at Washington, DC, on January 27, 2022.

**James P. Sheesley,**

*Assistant Executive Secretary.*

Dated at McLean, VA, this 9 day of May 2022.

**Ashley Waldron,**

*Secretary, Farm Credit Administration Board.*

**Melane Conyers-Ausbrooks,**

*Secretary of the Board, National Credit Union Administration.*

[FR Doc. C1–2022–10414 Filed 6–15–22; 8:45 am]

BILLING CODE 0099–10–P

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2022–0282; Project Identifier MCAI–2021–01208–R; Amendment 39–22087; AD 2022–13–01]

RIN 2120–AA64

**Airworthiness Directives; Leonardo S.p.a. Helicopters**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Leonardo S.p.a. Model AW169 helicopters. This AD was prompted by a report of a blockage in a fuel tank vent line. This AD requires inspecting the fuel tank vent lines, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective July 21, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 21, 2022.

**ADDRESSES:** For EASA material incorporated by reference (IBR) in this final rule, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. For Leonardo Helicopters service information identified in this final rule, contact Leonardo S.p.a. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39–0331–225074; fax +39–0331–229046; or at <https://customerportal.leonardocompany.com/en-US/>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2022–0282.

**Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No.

FAA–2022–0282; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:**

Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228–7330; email [andrea.jimenez@faa.gov](mailto:andrea.jimenez@faa.gov).

**SUPPLEMENTARY INFORMATION:****Background**

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021–0238, dated November 2, 2021 (EASA AD 2021–0238), to correct an unsafe condition for Leonardo S.p.a., formerly Finmeccanica S.p.a., AgustaWestland S.p.A., Model AW169 helicopters, serial numbers (S/N) from 69006 up to 69125 inclusive, except S/N 69040; and S/N 69130, 69132, 69133, 69134, 69136, and 69139.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Leonardo S.p.a. Model AW169 helicopters as identified in EASA AD 2021–0238. The NPRM published in the **Federal Register** on March 21, 2022 (87 FR 15894). The NPRM was prompted by a report of a blockage in a fuel tank vent line. The NPRM proposed to require inspecting the fuel tank vent lines, as specified in EASA AD 2021–0238.

The FAA is issuing this AD to detect and address the blockage. See EASA AD 2021–0238 for additional background information.

**Discussion of Final Airworthiness Directive****Comments**

The FAA received comments from two commenters. Commenters included AgustaWestland Philadelphia Corporation, who had no technical objection to the proposed AD, and an anonymous commenter who provided no comments on the proposed actions or on the determination of the costs.

**Conclusion**

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the